

Stopbank maintenance performance measure

Hutt River

Percentage of total stopbank length for each condition rating

Condition Rating	2006
1	89%
2	5%
3	0%
4	6%

Otaki River

Percentage of total stopbank length for each condition rating

Condition Rating	2006
1	95%
2	0%
3	0%
4	5%

Waikanae River

Percentage of total stopbank length for each condition rating

Condition Rating	2006
1	44%
2	0%
3	0%
4	56%

Guide to Condition Ratings

- 1 Meets required standard - scheduled maintenance only
- 2 Meets required standard - minor repairs required
- 3 Below required standard - specific repairs required
- 4 Below required standard - major repairs or renewal required